

Underground Updates

Presented by Quinn Malin

University of Alberta



Introduction

- ◆ This summer, PICO-500 has started shipping parts and assembling in SNOLAB
- ◆ The UofA and SNOLAB team have been working on this
- ◆ Main goals were to have everything shipped and in place for assembly, as well as start cleaning of the Jars
- ◆ Due to unfortunate events, there have been major setbacks in assembly underground, but we made the best of our time there

Shipping of Parts

- ◇ All major apparatus's have been shipped, cleaned, and setup in the Cryopit
 - ◇ Cleaning enclosures, Assembly table, Dishwasher, IV and Hardware, Practice Jars, Quartz handler, etc
- ◇ Several other parts have been processed underground as well:
 - ◇ Cameras, servers (some), Tools, UPW
- ◇ Quartz Handler was just recently sent underground (crucial for starting cleaning) as well as the IJ cleaning enclosure
- ◇ What's left?
 - ◇ Seals and pads for IV
 - ◇ Misc. Parts from UofA

Testing of Equipment

- ◆ PICO Helium Leak Checker:
 - ◆ Faulty Pressure sensor, now fixed and good to go
- ◆ Dishwasher Tests:
 - ◆ Initially damaged in shipment
 - ◆ New piping, temp sensors
 - ◆ Hooked up to air and UPW lines**
 - ◆ Works great, ready for cleaning
- ◆ Quartz Handler
 - ◆ Tested pressure and overall movements of parts
- ◆ Chillers (top and camera)
 - ◆ Damage in shipping, multiple tests done with load
 - ◆ No issues found, testing has been closed out
- ◆ Microscope for sample analysis
 - ◆ Works great
- ◆ Assembly Table testing
 - ◆ Completed full inspection and cleaned

Cleaning









Assembly Table

- ◆ Installed underground
 - ◆ No problems in installation
 - ◆ No parts damaged


- ◆ Do we need to bolt this down to the floor?



Particle Counts

- ◇ Fairly low in CR without movement
 - ◇ Multiple people working inside causes a lot more particulates
 - ◇ We need to produce a full procedure for cleaning before we enter the cleanroom (Ashley)

- ◇ Particulate counts in BAD (back access drift) are very BAD
 - ◇ Well over 1000 counts/ft³ for 0.5um and 5um
 - ◇ Largely due to holes in the door between lab and drift
 - ◇ Recently patched, but should be considered when transporting parts through the area
 - ◇ Mitigated with Radon bag?



Future Plan

- ◆ David and I are arriving Sept 4th for a month, and probably a subsequent trip
- ◆ Plan on cleaning of practice jars
 - ◆ I would like to expedite this process so we can start cleaning the real jars
- ◆ After cleaning the fake jars, I'd like to do a test assembly
 - ◆ This will allow us to do leak tests, a test movement of the IV from Cryopit to CubeHall, and get everyone familiar with the lifts who aren't
- ◆ Radon Mitigation
 - ◆ Jeremy is planning on coming sometime in September too
- ◆ Cleaning of the bellows
 - ◆ Hasn't been thought of, but recently planned out and going to test this coming month.
- ◆ PV cleaning
- ◆ UPW line parts are processed, expected to be installed next week

Important Questions


- ◆ Plan is to have the IV assembly done by December (just components from UofA)
- ◆ We need to have the IV under N2 flush until its inserted into the PV, which could be months
 - ◆ When is the PV built, should we hold off some of the assembly?
- ◆ Perhaps we build a large enclosure to hold the IV in an N2 environment
 - ◆ Something just lowered on top, seals with the floor.
- ◆ Piezo installation?
 - ◆ Is this on the assembly table or BFAT?
 - ◆ When is production done?
 - ◆ Could increase time of N2 flush on IV

Questions?


Extra slides

UPW line samples

Mini clean UPW



After 5 min purge



Testings Underground

- ◇ After PICO He leak checker was fixed, we performed leak tests on the bellows and surrounding parts
- ◇ Known leak on the IV assembly
 - ◇ ****Part is not going in final assembly****



Leaks

- ◇ Sniffing test is far less accurate
- ◇ One major leak located (possibly in same position as the one before but needs to be confirmed)
- ◇ Leak checked all of bellows, only leak near the A1 flange (with know leak)
- ◇ Reached roughly $2.5 \cdot 10^{-4}$ mbar 1/s

